

AA Working Ranges

The lower limit of the working range is approximately ten times the detection limit.

Aurora Instruments

www.aurora-instr.com

Aurora Instruments Ltd.
1001 East Pender St.
Vancouver, B.C.
Canada, V6A 1W2
Tel: (604)215-8700,
Fax: (604)215-9700
Toll Free:1-800-883-2918
Email: aurora@intergate.bc.ca